

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210

Box 145801

Salt Lake City, Utah 84114-5801

Telephone: (801) 538-5291

Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1-1-04 To (mo./yr.) 12-31-04
2. DOGM File Number (Mine No): 5550623
3. Mine Name: Lucero Red - North
4. Mineral(s) Mined (or permitted to mine): Sandstone
5. Type of mine: ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
____ 1/4, ____ 1/4, ____ 1/4, Section 13, Township 29S, Range 4E
____ 1/4, ____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
____ 1/4, ____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
7. Name of Operator or Company: Quality Building Stone, Inc.
8. Permanent Street Address: 993. 14730 W.
City, State, Zip: Bluffdale, Utah 84065
Phone: (801) 255-2911 Fax: _____
9. Company Representative (or designated operator):
Name: Weston Hansen
Title: Production Manager
Business Address: 993. 14730 W.
City, State, Zip: Bluffdale, Utah 84065
Phone: (801) 255-2911 Fax: _____

☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☐ No ☒
2. If no - what was the last year of activity? 2003
3. If yes - how much ore or mineral was mined? None

Reviewed
2/19/05
PJB

Average discrepancy
noted.

RECEIVED
FEB 10 2005
DIV. OF OIL, GAS & MINING

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.

- None -

5. How much **additional acreage** was disturbed during the past year? - None -

6. How much acreage was **reclaimed** during the past year? approx. 2 acres

7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

Bulldozing, clearing of blocks/rocks.

8. What is the **total** disturbed acreage of entire project at years end? approx. 2 acres

9. Briefly summarize any mining and/or reclamation plans for the upcoming year.

Mining as per market conditions for this rock.

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information - R647-4-121.2 and .3

1. The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Weston Hansen

Title of Operator: Production Manager

Signature of Operator: Weston Hansen

Date: 2-10-05